

07:42:00 CLR Call Monitor: Call RSSI value  
 4113 Source: 6 CCP0  
                   (407)3250010 cell 201 frssi -81 rrssi -83 attn 2  
                   fber 0 rber 0 Object: 20 A TC 780  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 BTS:1 Chassis: Slot:0 Port:  
 007:42:00 CLR Call Monitor: Adjacent cell RSSI values from mobile  
 4116 Source: 6 CAP2  
                   (407)3250010 Cell\_id/RSSI: 32/-97 202/-113 491/-103  
                   Object: 6 CAP2  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 Chassis:6 Slot:11 Port:  
 07:42:00 CLR Call Monitor: Adjacent cell RSSI values from mobile  
 4116 Source: 6 CAP2  
                   (407)3250010 Cell\_id/RSSI: 412/-87 323/-109 203/-103  
                   Object: 6 CAP2  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 Chassis:6 Slot:11 Port:  
 007:42:00 CLR Call Monitor: Adjacent cell RSSI values from mobile  
 4116 Source: 6 CAP2  
                   (407)3250010 Cell id / RSSI: 1353/-113  
                   Object: 6 CAP2  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 Chassis:6 Slot:11 Port:  
 07:42:01 CLR Call Monitor: Call RSSI value  
 4113 Source: 6 CCP0  
                   (407)3250010 cell 201 frssi -81 rrssi -84 attn 2  
                   fber 0 rber 0 Object: 20 A TC 780  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 BTS:1 Chassis: Slot:0 Port:  
 007:42:01 CLR Call Monitor: Call Handoff has taken place  
 4104 Source: 2 CCP0  
                   Ph#: (407)3250010 Handoff from 201 to 32  
                   Object: 3 B TC 755  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:1 BTS:2 Chassis: Slot:0 Port:  
 07:42:01 CLR Call Monitor: Call Path Assigned  
 4101 Source: 2 CCP0  
                   Ph#: (407)3250010 Handin connect El: 0, 7 T1: 0, 4  
                   755 TDMA-3 Object: 3 B TC 755  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:1 BTS:2 Chassis: Slot:0 Port:  
 007:42:01 CLR Call Monitor: Adjacent cell RSSI values from mobile  
 4116 Source: 6 CAP2  
                   (407)3250010 Cell\_id/RSSI: 32/-97 202/-113 491/-101  
                   Object: 6 CAP2  
                   Class: XXXXXXXXXXXXXXXX  
                   Domain:2 Chassis:6 Slot:11 Port:

Figure 1

20062014205 - 0002600




Figure 2

## STANDARD FILE FORMAT

Subscriber Number

Serving cell site

Channel

Channel type

Mobile power

F\_RSSI<sub>1</sub>, F\_RSSI<sub>2</sub>, ..., F\_RSSI<sub>n</sub>

R\_RSSI<sub>1</sub>, R\_RSSI<sub>2</sub>, ..., R\_RSSI<sub>n</sub>

F\_BER<sub>1</sub>, F\_BER<sub>2</sub>, ..., F\_BER<sub>n</sub>

R\_BER<sub>1</sub>, R\_BER<sub>2</sub>, ..., R\_BER<sub>n</sub>

Call\_event<sub>1</sub>, Call\_event<sub>2</sub>, ..., Call\_event<sub>n</sub>

NEIGHBOR\_RSSI<sub>1</sub>, NEIGHBOR\_RSSI<sub>2</sub>, ..., NEIGHBOR\_RSSI<sub>n</sub>

TimeStamp<sub>1</sub>, Lat/Long<sub>1</sub>, ..., TimeStamp<sub>n</sub>, Lat/Long<sub>n</sub>

:

:

:

Figure 3

- [ ] X







Figure 4a



## Figure 4B






Figure 6




Figure 7